




FIG. 2




2/5














MAGNETORESISTIVE SPIN-VALVE SENSOR...

Kong et al.

Greer, Burns & Crain, Ltd. (Patrick Burns)

Rof. No. 0941.68363

Sheat 4 of 5 (312) 360 0080

4/5

FIG.7





FIG.8



5/5

FIG. 9




FIG. 10

